

LIEBHERR LADERAUPE LR 636

??????? ???? ?		BILDER
?? ?	18147	 
?? ?	2015	
???? ?	10526	
???? [??]	24	
???? ?		 
????	Liebherr	
?? ?	D934 A7-14	
?? ?	135	
?? ?????	Tier 4 Final	
???? ? [????]	10129h / 31.10.22	 
???? (????)	✓	
???? ?	✓	
???? ?		
???? ?		
???? ?		
???? ? [??]	560	
???? ? [³]	2,5	
???? ?	✓	

??????			
??????	??????	???????	???
?? ?????	✓		
??????	✓		
??? ?????	✓		
??? ??????	✓		
?????	✓		
??????	✓		
??????	✓		
????? ?????	✓		
???????	??????	???????	???
??????	✓		
?????	✓		
???????	✓		
???????	✓		
???????	✓		
???????	✓		
???????	✓	Anflanschung der Arbeitshydraulikpumpe leicht schwitzig	
????? ?????	✓		
??????/?????	??????	???????	???
???????	✓		
??????/ ??????	✓		
??????	✓		
????? ????	✓		
???????	✓		
?????? ?????	✓		

????????	??????	????????	???
????????	✓		
???? ?????	✓		
????????	✓		
????????	✓		
?????? ??????	✓		
????????	??????	????????	???
?????	30%		
????? ?????	70%		
????? ???????	70%		
?????? ????????	60%		
????????	??????	????????	???
????	80%		
????	??????	????????	???
??????/???	✓		
?????/?????	✓		
???? ???????	✓		
?????	✓	Schloss von Seitenklappe VL defekt	
?????	✓		
????	✓		