

HAMM KOMBIWALZE HD 10 VT

GENERAL		BILDER
ID	16942	     
Year	2015	
Working hours	5	
Weight [to]	2,385	
Manual	✓	
Spare part book	✓	
CE conformity	✓	
ABE	✓	
ENGINE SPECIFICATION		
Manufacturer	Kubota	
Engine [type]	D1503	
Engine rating [kW]	22,9	
Emission standard	EU Stage IIIA	
last service [h]	3h / 26.01.18	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		

HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		
UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Tires bl	100%		
Tires br	100%		
WEAR	STATUS	REMARKS	PICTURES
Scraper	100%		
drum rubbers	100%		
Drum	100%		

OTHERS	STATUS	REMARKS	PICTURES
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		