

LIEBHERR LADERAUPE LR 636

GENERAL		BILDER
ID	18147	 
Year	2015	
Working hours	10526	
Weight [to]	24	
		 
		 
ENGINE SPECIFICATION		
Manufacturer	Liebherr	
Engine [type]	D934 A7-14	
Engine rating [kW]	135	
Emission standard	Tier 4 Final	
last service [h]	10129h / 31.10.22	
EPA	✓	
exhaust gas after-treatment	✓	
EQUIPMENT		
track pad [mm]	560	
Bucket [m³]	2,5	
Air-conditioning	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓	Anflanschung der Arbeitshydraulikpumpe leicht schwitzig	
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
sglass pane	✓		
Display / buttons	✓		
AC	✓		
Heating	✓		
General condition	✓		

ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		
UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	30%		
Track roller	70%		
Link assy	70%		
Pads	60%		
WEAR	STATUS	REMARKS	PICTURES
Other	80%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓	Schloss von Seitenklappe VL defekt	
Axles	✓		
Other	✓		